

RUST X REMOVER PHOSPHATIZER

RUST REMOVER

- *Removes Rust
- *Prevents Re-Rusting
- *Phosphatizes Metal
- *Improves Paint Adhesion
- *Non-Flammable

CAUTION Keep out of reach of children. Product is Poison. May be fatal if ingested.

35B09 Net Contents: Gallon(s)

This concentrated blend of inorganic acids, wetting agents, detergents, and water softeners is specifically designed for the rapid removal of rust while providing long term protection against further rusting by providing a resistant phosphate surface on ferrous metals. The detergent action helps to remove grease and oils which have accumulated on the metal surface. Phosphatizing offers a very conductive surface for metals which are to be painted following the removal of rust.

DIRECTIONS FOR USE

For rust removal, dilute concentrate with water at a rate of 1:3. Solution may be applied by soaking, brushing, or spraying onto surface. Treatment time will vary depending on the extent of rust to be removed. Usually the process may be accomplished within 30 minutes, but solution may remain on surface for longer periods if required. Often it may be necessary to make a second application if rusting is extensive. Do not rinse. As a phosphating and rust preventative treatment, dilute concentrate with water at a rate of 1:30. Apply to surface by spraying, brushing or soaking. Allow to air dry, do not rinse. This product will etch glass or porcelain surfaces. If contact occurs rinse with water immediately.

CAUTION: Keep out of reach of children. **DANGER**: This product is poison. The product contains inorganic acids and can cause severe burns if used improperly. Avoid direct skin contact. Wash effected areas with soap and water. Eyes: Flush with water for 15 minutes and contact physician. Ingestion: Do not induce vomiting. Drink milk of magnesia or egg whites beaten with water. Consult physician. Wear protective clothing when using this product. Rinse container before disposal.

To Reorder

PIC

4408 McLEAN • FORT WORTH, TEXAS 76117 (800) 359-8031