

CLEAN STRIP HEAVY DUTY CLEANER

**EXTRA HEAVY DUTY
CLEANER**

FOR ALL DEPARTMENTS

USDA APPROVED

CAUTION:

Irritant. Harmful if swallowed. Carefully read all cautions.

77D80	NET CONTENTS	POUND(S)
--------------	---------------------	-----------------

**TO REORDER
PIC**

4408 Glenview Dr
Haltom City, TX 76117
817-281-1474 1-800-359-8031

Clean Strip is a highly alkaline product which strips fats, dirt, grease, oil and carbon deposits from ferrous, cupreous alloyed and stainless steel surfaces. It contains detergents to give maximum solution life, penetration and rinseability. Clean Strip is USDA approved and can be used for general cleaning in all departments.

DIRECTIONS:

For machinery, belting and food process equipment: Mix 8 to 16 ounces of Clean Strip per gallon of water. Maintain water temperature at 140 degrees F. For concrete floors, walls, tile walkways, etc use 4 to 6oz of Clean Strip per gallon of water. Add Clean Strip slowly to avoid splattering. **NOTE:** CLEAN STRIP will bloom aluminum if used in high concentrations. Rinse thoroughly after use.

CAUTIONS: Keep out of reach of children. Do not take internally.

CLEAN STRIP contains Sodium Hydroxide and can cause severe burns to skin and eyes. When handling, wear goggles, rubber gloves and an apron. In case of skin contact, flush with water for 15 minutes. For eyes, flush with large amounts of water for 15 minutes and seek medical attention.